



SCHEMATIC

NOTE: OVERLOAD RESET MOUNTED IN COVER

MOTOR POWER DISCONNECT OFF ON

MOTOR POWER IN

L1 T1 BK

L2 T2 BK

L3 T3 BK

O/L

O/L

O/L

BK

2 OP 1 GY

BK 4 OP 3 GY P

BK 6 OP 5 P

WH 120VAC PRIMARY BK

2 CL 1 Y

4 CL 3

6 CL 5

INTERNAL MOTOR CONNECTIONS

230V - 3 PH MOTOR CONNECTION

TO MOTOR

7 1 0 (GY)

8 2 0 (PU)

9 3 0 (YE)

7 1 0 (GY)

8 2 0 (PU)

9 3 0 (YE)

Fig 4